

RUSSELL & AXON



Established in 1920

Engineers • Planners • Architects  
Incorporated

RECEIVED

AUG 6 1984

WATC

A.2  
8/3/84  
153817

August 3, 1984

Mr. E.G. Clawson  
Walbridge, Aldinger Co./  
Tarlton Corporation  
#1 American Bottoms Road  
Sauget, Illinois 62201

Re: 00087  
File No. A1.20  
Log No. 971

Dear Mr. Clawson:

Attached you will find a report from Clayton Environmental Consultants, Inc. (Industrial Hygienists). Included in their report are the results of analyses of two samples of the black material encountered during installation of the 16" water line. As can be seen, it is primarily oil and grease; however, it does have quantities of PCBs.

In view of the fact that this material was highly concentrated and had a tar-like consistency and workers were in the area for only 1 to 2 hours, it is our conclusion that no one was endangered (by direct contact or airborne exposure) in any way from the material encountered.

As you know, the area was covered with clean dirt shortly after discovery and it is to be covered by you with at least another two feet of fill before construction of the road. Prior to your resuming work in the area, we will again walk the site with you and make sure no material is exposed. It is imperative, however, during your road work that only filling occurs, not excavation. Therefore, please inform all of your personnel and subcontractors accordingly.

006844

0000000000

Very truly yours, .

William Lago

WLS/s1b

cc: Mr. Jim Gorry  
Mr. John R. Zelle  
Mr. Paul H. Darmer  
Mr. Dennis R. Herzing

**Attachment**

55